Landlords / Homeowner Gas Safety Record - G2



Gas-elec Group Summer Road. Walsham - Le - Willows. Bury St Edmunds. IP31 3AJ



Next expiry date: Tuesday, 1 February, 2022 Client: Paraden Limited 13 Planetree Road Hale

Cheshire

WA15 9JL

Access Date:

Monday, 1 February, 2021

Site Add.: 8 Mount Pleasant Wilmslow Cheshire

SK9 4AP

Cert. No: CT-510027-1677614001

Gas Inspection Details ****(There is an Advisory Situation for this installation, please see the comments page for full details)***									
Meter Reading	Meter / ECV Location	AECV location (if app)	Meter Visual Inspection	Meter Type	ECV Accessible	Gas Installation Pipework	Let-By/Tightness Test	Record Pressure Drop	Protective Earth Bond
40004		N/A		0.4				٥	

12684	12684 Lounge Cupboard		Pass		G4	Yes	Pass		Pass / Pass	0		Yes	
Gas Applianc	e Details	Boiler			Hob								
Location	ocation Airing Cupboard			Kitchen									
Make	Make Glow-worm			AEG									
Model #		Easicom 28	icom 28		Not Found								
Serial #	erial # 21141100100136511300134606N7			Not Found									
Flue Type		Room Sealed			Flueless								
Safety Device		N/P			N/P								
Operating Pres	ssure/Gas Rate	28.00 kW (NETT)			21.00 mbar								
Ventilation Ade	equate	Yes			Yes N/A N/A N/A								
Flue Flow Test	t	N/A											
Spillage Test		N/A											
Termination Sa	atisfactory	Yes											
Visual Condition	on	Pass			Pass								
Appliance Serv	viced	No			No								
ID, AR or Advis	sory situation	Advisory Situation			Advisory Situation .								
Gas Council N		4701919											
Flue Gas Analy	ysis (Ratio)	0.0008			N/A - This applia	nce is not a boiler							
Safe To Use		Yes			Yes								
Fuse / Electrica	al	Safety Isolated			Safety Isolated								
Appliance relate	Appliance related comments: Boiler found faulty. System pressure increased from zero. Left working.		Burner ignition fa	ulty.									

In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint, gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. A detailed internal inspection of the flue integrity, construction and lining has not been carried out. I confirm that the situation(s) recorded above, has been identified and brought to the attention of the Responsible Person in accordance with the GSIUR, and Gas Industry Unsafe Situations Procedure. This report has been completed and issued by Gas-elec Safety (UK) Ltd.

This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures. A copy of this working method statement can be found on: www.gas-elec.co.uk/cvd19

Next Inspection Due Within 12 Months

(Please refer to 'General Comments' page for comments made by the engineer regarding the installation)

This Safety Record Issued By

I. Caldwell.

Name Ian Caldwell

Landlords / Homeowner Gas Safety Record - G2



Gas-elec Group Summer Road, Walsham - Le - Willows, Bury St Edmunds, IP31 3AJ



Access Date: Monday, 1 February, 2021 Next expiry date: Tuesday, 1 February, 2022

Client: Paraden Limited 13 Planetree Road Hale Cheshire WA15 9JL Cert. No: CT-510027-1677614001

Site Add.: 8 Mount Pleasant

Wilmslow
Cheshire
SK9 4AP

General comments (Advisory situation):

Advise: gas meter not fixed to the fabric of the building.

Annual Electrical Safety Record - E2



Gas-elec Group Summer Road, Walsham - Le - Willows, Bury St Edmunds, IP31 3AJ Continuity Insulation

Passed

INSTALLATION INSPECTION (Visual & Functional)								
Electrical supply details							Meter Reading: N/A	
Type: TN-S	PIR/EICR	Label present Yes	Expires on 07/11/2022	Meter Visual Inspection: Pass				
Main Earthing Conductor	Main Protective Bonding Conductors				General Condition of C	Consumer Unit: Good	Consumer Unit Location:	Lounge cupboard
Present	Water: Yes Gas: Yes Ott	ner:			RCD Test: Yes	RCD Operating times X1: 21 X5: 14	Zs 0.50 Ω	
Circuit Number Description	on	Functional Check	Protective Device	Recommendati	ions			

Circuit Number	Description	Functional Check	Protective Device	Recommendations
1	Socket outlets Throughout	Yes	BS (EN) 60898	RCD(1) protected circuit.
2	Socket (spur)	Yes	BS (EN) 60898	RCD(1) protected circuit.
3	Lighting throughout	Yes	BS (EN) 60898	RCD(2) protected circuit.
4	Socket (spur)	Yes	BS (EN) 60898	RCD(2) protected circuit.

APPLIANCE DETAILS/ ELECTRICAL EQUIPMENT RESULTS

ID Location	Туре	Make	Model	Serial No	Plug	Flex	Body	(ohms)	(megohms)	Check	Comments	Safety Test
1 Kitchen	Oven/Grill	Cookerexcels	CLE01BKC	Not Found	Pass	Pass	Pass	0.05	20	Pass	None	Yes
2 Kitchen	Hob	AEG	Not Found	Not Found	Pass	Pass	Pass	0.1	20	Fail	None	Yes
3 Kitchen	Cooker Hood	Blanco	0004321	Not Found	N/Acc	N/Acc	Pass	N/A	N/C*	Pass	Class 2	Yes - VO
4 Kitchen	Fridge	Lec	R5511W	70601415444441000	Pass	Pass	Pass	0.06	20	Pass	None	Yes
5 Utility Room	Washing Machine	Hotpoint	FDEU8640	706141821	Pass	Pass	Pass	0.05	20	Pass	None	Yes

Details of any faults found and rectification work necessary	Warning Notice	rning Notice		
1	No	This Safety Record Issued By:		
2 Appears faulty.	No			
3	No	10.00		
4	No	I. Caldwell.		
5	No	9.0		
		Engineer Name: Ian Caldwell		

Next Inspection Due Within 12 Months

The report is a general, visual, surface and functional examination of the electrical system, which is accessible i.e. visible and readily available for inspection from ground and floor levels without risk of causing damage to the property or injury to the inspector and limited accordingly. Due care is therefore exercised throughout the inspection regarding safety, practicality and the constraints of being a visitor to to the property (which may be occupied). So furniture, floor coverings and other contents are not moved, lifted and no part is forced or laid open to make it accessible. Loop impedance tests are only carried out on socket outlets. The report is provided solely for the use of the client and no liability to anyone else is accepted. Should the client not act upon specific advice contained in the report, or esponsibility is accepted for the consequences. Gas-elec Safety (UK) Ltd, its membrages accept no liability for the consequences of any errors or omissions in this report. THIS IS A VISUAL AND FUNCTIONAL INSPECTION ONLY. In the event of a complaint relating to any service or installation in a property gas-elec must be given the opportunity to address the issue by re-visiting the property to resolve any alleged complaint. gas-elec cannot be held responsible if the opportunity to fully address the matter is not afforded to us. In the event of another company/contractor being called to the property to investigate or attempt to rectify an alleged complaint in preference to gas-elec the company will accept no liability. Where passed safety test is VO, this is an abbreviation of visual only inspection. This report has been produced in accordance with the Gas-Elec Group working method statement which covers COVID -19 virus procedures. A copy of this working method statement can be found on: www.gas-elec.co.uk/cvd19